Release Notes

IMPORTANT: the firmware update cycle can take up to 10 minutes, and the device may reboot twice during update process.

Public Release

Version 1.0.37	
Features	• Added a signal filtering option for the Mic mute button on ceiling microphone, enabled by default.

Previous Releases

Version 1.0.24	
Features	• Save the ceiling mic mute status, the default is unmute; • Resolve the bug when USB volume “0”, it is possible to mute from Wireless mic • Resolve the bug when power circuit device, the IP address from DHCP mode happen changing. • Supports the Telnet API separator， including 0x0d,0x0a,0x0d0x0a; • Under auto IP mode, the IP address is set as 169.254.1.100; • Other improvements for increasing robustness.

Version 1.0.18	
Features	• Factory Firmware